

# Mortared walls

## Before...

## After...




Collapse after storm. Lime mortared retaining wall in Conservation Area.



New wall & patio re-laid



Damaged steps, railings, driveway & wall from burst water main



Collapsing retaining wall

